



Completed on behalf of a general contractor upgrading a retail fuel outlet in Radisson, SK

Concentric Geoscience was retained to oversee remediation requirements and coordinate a geotechnical investigation as part of a new canopy installation at a retail fuel outlet in Radisson, Saskatchewan. Several areas of impact were identified in the project area associated with legacy contamination from past operations. This resulted in the need for multiple remedial excavations. Concentric Geoscience field personnel oversaw each remedial excavation, coordinated extensive groundwater control measures and, verified remedial targets in advance/support of the site construction.